


U598 RADIO RECEIVER

www.radio-workshop.co.uk

U598



COPYRIGHT. SUBJECT TO ALTERATION WITHOUT NOTICE. ISSUE H

Circuit voltages are shown within rectangles and were measured with a 20,000 Ω/V meter while the receiver was switched to the M band under no-signal conditions. Where the resistance of a coil is less than one ohm the value is omitted.

Component terminals and connecting leads are identified by test point (t.p.) numbers which correspond with those appearing on the chassis drawings. The valve pin numbers are shown within small circles.